

Inspection Photos

January 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325088

Inspection Document #: 714001677

La Plata County, CO

Township: NENW 36 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wilde B1
Location ID: 325088




Photo 1. View of well location taken from the access point facing center.

Inspection Photos
Location Name: Wilde B1
Location ID: 325088



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Weedy russian thistle debris observed on location.

API #: 067-05244

Inspection Photos
Location Name: Wilde B1
Location ID: 325088



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of eastern interim reclamation area composed of Western Wheatgrass and Squirrel Tail.

API #: 067-05244

Inspection Photos
Location Name: Wilde B1
Location ID: 325088



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of pasture reference area.

API #: 067-05244