

Inspection Photos

January 7th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 311917

Inspection Document #: 714001679

La Plata County, CO

Township: SWSE 26 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Docar Gas Unit 2
Location ID: 311917

1/7/25
286° W



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Docar Gas Unit 2
Location ID: 311917



Photo 2. View of the eastern interim reclamation area composed of Indian Ricegrass, Sagebrush and Juniper.

Inspection Photos
Location Name: Docar Gas Unit 2
Location ID: 311917



1/7/25
209° SW