

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025



Photo # 1997 Entrance to location




Photo # 2028 Location



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025




Photo # 1998 Location



Photo # 2003 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025



Photo # 2026 Location




Photo # 2034 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025



Photo # 2035 NE corner of location



Photo # 2036 SE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025




Photo # 2037 SW corner of location




Photo # 2011 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025



Photo # 2014 Wildlife hazard



Photo # 2020 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025




Photo # 2022 Wildlife hazard



Photo # 2023 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC TRAIL RIDGE-65S97W/36NESW (TR 6-36 PAD)

Location ID: 323832

Date: 01/6/2025



Photo # 2031 Open ended load line



Photo # 2033 Open ended load line