

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14NENE

Location ID: 334814

Date: 1/8/2025



Location Overview – Photo #05839



Location – Photo #05840

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14NENE

Location ID: 334814

Date: 1/8/2025



Location – Photo #05841

Location – Photo #05843

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14NENE

Location ID: 334814

Date: 1/8/2025



**Insufficient Erosion Controls/Ditch Needs Maintenance –
Photo #05845**



**Insufficient Erosion Controls/Ditch Needs Maintenance –
Photo #05846**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/14NENE

Location ID: 334814

Date: 1/8/2025



**Insufficient Erosion Controls/Ditch Needs Maintenance –
Photo #05847**



**Insufficient Erosion Controls/Ditch Needs Maintenance –
Photo #05848**