

**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-34 (RI1) Pad**  
**Location #: 334572**



**Photo # 7201 From entrance to location**



**Photo # 7202 Location**

**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-34 (RI1) Pad**  
**Location #: 334572**



**Photo # 7203 Location**



**Photo # 7204 Location**



**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-34 (RI1) Pad**  
**Location #: 334572**



**Photo # 7205 Location**



**Photo # 7206 Location**

## Inspection Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



**Photo # 7207 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**



**Photo # 7208 Open ended load line**



**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-34 (RI1) Pad**  
**Location #: 334572**



**Photo # 7209 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 7210 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



**Photo # 7211 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 7212 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



**Photo # 7213 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 7214 Barbed wire fence needs maintenance/wildlife hazard**



**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-34 (RI1) Pad**  
**Location #: 334572**



**Photo # 7215 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 7216 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection Photos

Location Name: QB Energy SAVAGE 1-34 (RI1) Pad

Location #: 334572



**Photo # 7217 Barbed wire fence needs maintenance/wildlife hazard**