

Final Reclamation and Stormwater Inspection

Date: 01/09/2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 306473

Inspection Document #: 708201923

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wells Ranch USX AA 19-23
Location ID: 306473



Photo 1. Photo from FIR (doc #696100614) conducted 03/23/2019, approximately 4 months after plugging and abandonment operations. Photo illustrates an access road west/left of the existing access road. It is unsure whether the access road (indicated by red arrow) is from P&A operations and/or flowline removal.

Inspection Photos
Location Name: Wells Ranch USX AA 19-23
Location ID: 306473




Photo 2. Drone aerial imagery taken from the drone closure report (doc #404017506; Page 19). Photo illustrates areas of non-uniform vegetation cover resulting in bare soils. A follow-up inspection will be conducted at a later date to assess the disturbance areas.