

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2040 Entrance to location



Photo # 2062 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025




Photo # 2042 Location



Photo # 2047 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Jan 6, 2025 at 2:22:14 PM
+39.560241,-108.249011 ±4.93m

Photo # 2061 Location



Jan 6, 2025 at 2:55:29 PM
+39.560196,-108.249630 ±2.98m
De Beque

Photo # 2110 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2111 SW corner of location



Photo # 2115 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2116 SE corner of location




Photo # 2055 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2074 Open ended load line



Photo # 2075 Open ended load line



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2076 Open ended load line



Photo # 2077 Open ended load line

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2078 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 2094 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2096 Storage of miscellaneous supplies, and equipment



Photo # 2100 Storage of miscellaneous supplies, and equipment

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2103 Storage of miscellaneous supplies, and equipment



Photo # 2107 Storage of miscellaneous supplies, and equipment

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2056 Debris



Photo # 2060 Debris

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC SHELL-66S97W/5NWNW (SHELL TR 11-5-697 PAD)

Location ID: 324409

Date: 01/6/2025



Photo # 2105 Debris



Photo # 2106 Debris