

Inspection Photos

01/08/2025

Operator: VISION ENERGY LLC - 10770

Location ID: 312553

Inspection Doc: 718100152

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos show final reclamation has not been performed in accordance with 1004 requirements- Location/Road has not been decompacted, recontoured/regraded and reclaimed; Undesirable and Noxious Plant Species (Halogeton) observed established throughout the Location disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 3: Photo taken from the southwest end of the Location, facing north and east. Photos show fill slopes; Location has not been decompacted, recontoured/regraded and reclaimed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 4: Photos 4-5 taken from the north end of the Location. Photos provide an overview of the Location from east. southeast, southwest to west. Photos show final reclamation has not been performed in accordance with 1004 requirements- Location/Road has not been decompacted, recontoured/regraded and reclaimed; Undesirable and Noxious Plant Species (Halogeton) observed established throughout the Location disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



January 8, 2025



January 8, 2025

Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 6: Photo taken from the northeast corner of the Location, facing west. Photo shows the cut slopes; Location has not been decompacted, recontoured/regraded and reclaimed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312553



Photo 7: Photo taken from the northwest end of the Location, facing north. Photo shows access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources