

Inspection Photos

01/08/2025

Operator: VISION ENERGY LLC - 10770

Location ID: 312383

Inspection Doc: 718100156

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312383



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Photos show final reclamation has not been performed in accordance with 1004 requirements- Location has not been decompacted, recontoured/regraded and reclaimed; Undesirable and Noxious Plant Species (Halogeton) observed established throughout the Location disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312383



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312383



Photo 3: Photos taken from the south end of the Location. Photos provide an overview of the Location from northwest to north. Photos show final reclamation has not been performed in accordance with 1004 requirements- Location has not been decompacted, recontoured/regraded and reclaimed; Undesirable and Noxious Plant Species (Halogeton) observed established throughout the Location disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 312383



Photo 4: Photo shows surface equipment (riser) remaining on the north end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources