

Operator: CPR

Location Name: GEIST MULTI WELL PAD 0-2-32

Loc ID: 331851

Inspection: 716201339





CA: Weed debris at wellhead. Comply with Rule 606

CA Resolution: Operator has appropriately cleared weeds/debris from the wellhead to comply with 600 series.