

## Inspection Photos

Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad

Location #: 334616



Photo # 8200 From entrance to location




Photo # 8201 Location



**Inspection Photos**  
**Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad**  
**Location #: 334616**



**Photo # 8202 Location**



**Photo # 8203 Location**





## Inspection Photos

Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad

Location #: 334616



Photo # 8204 Location




Photo # 8205 Location

## Inspection Photos

Location Name: QB Energy PARKER RANCH 22-7 (G22) Pad

Location #: 334616



Photo # 8206 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 8207 PRV vent line does not comply with CECMC pressure safety device rules