

Inspection Photos  
Location Name: Crossland 11-28  
API Number: 125-08792



1. Lease sign at well location.




2. View of wellhead.

**Inspection Photos**  
**Location Name: Crossland 11-28**  
**API Number: 125-08792**



**3. Well location overview.**



**4. Lease sign at gathering location.**



**Inspection Photos**  
**Location Name: Crossland 11-28**  
**API Number: 125-08792**



**5. Gas meter inside meter shed.**



**6. Gathering location overview.**