

Inspection Photos  
Location Name: Crossland 5-28  
API Number: 125-07562



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Crossland 5-28**  
**API Number: 125-07562**




**3. View of domestic tap at well location.**



**4. View of domestic tap and wellhead.**

Inspection Photos  
Location Name: Crossland 5-28  
API Number: 125-07562



5. Lease sign at gathering location.



6. Dehydrator on flowline inlet to meter shed.

**Inspection Photos**  
**Location Name: Crossland 5-28**  
**API Number: 125-07562**



**7. Gas meter inside meter shed.**



**8. Gathering location overview.**