

Inspection Photos
Location Name: Crossland 43-28 5N46W
API Number: 125-09827



1. Lease sign at well location.



2. View of wellhead.


Inspection Photos

Location Name: Crossland 43-28 5N46W

API Number: 125-09827



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: Crossland 43-28 5N46W
API Number: 125-09827



5. Gas meter inside meter shed.



6. Gathering location overview.