

**Inspection Photos**  
**Location Name: Crossland 32-33 5N46W**  
**API Number: 125-09791**



**1. Lease sign at well location.**



**2. View of wellhead.**


## Inspection Photos

Location Name: Crossland 32-33 5N46W

API Number: 125-09791



3. Well location overview.



4. Lease sign at gathering location.



**Inspection Photos**  
**Location Name: Crossland 32-33 5N46W**  
**API Number: 125-09791**



**5. Gas meter inside meter shed.**



**6. Gathering location overview.**