

# Final Reclamation and Stormwater Inspection

Date: 01/10/2025

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 306270

Inspection Document #: 708201929

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: State Pronghorn 11-16  
Location ID: 306270



**Photo 1.** Facing southwest at the start of the access road. It appears that the access road has been contoured and graded to reflect the adjacent topography and the disturbance areas have been reseeded.

Inspection Photos  
Location Name: State Pronghorn 11-16  
Location ID: 306270




**Photo 2.** Facing north near the former well and tank battery location. It appears that road base material has been removed and the disturbance areas have been contoured and reseeded with evidence of drill rows and crimped mulch (much of the straw appears to have blown away).

Inspection Photos  
Location Name: State Pronghorn 11-16  
Location ID: 306270



**Photo 3.** Facing east near the former well and tank battery location; see comments in Photo 2.

Inspection Photos  
Location Name: State Pronghorn 11-16  
Location ID: 306270



**Photo 4.** Facing south near the former well and tank battery location; see comments in Photo 2.

Inspection Photos  
Location Name: State Pronghorn 11-16  
Location ID: 306270



**Photo 5.** Facing west near the former well and tank battery location; see comments in Photo 2.