

# Final Reclamation and Stormwater Inspection

Date: 01/10/2025

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 305141

Inspection Document #: 708201931

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 1.** Facing south at the start of the access road. It appears that the former access road has been contoured and graded to match the surrounding topography. The disturbance areas also appear to have been drill seeded and mulched.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 2.** Facing north from the access road, near the former well location. See comments in Photo 1.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 3.** Facing east near the former well location. The disturbance areas appear to have been reseeded with crimped mulch and drill rows observed.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 4.** Facing south near the former well location. See comments in Photo 3.

Inspection Photos  
Location Name: Pronghorn 11-17  
Location ID: 305141



**Photo 5.** Facing west near the former well location. See comments in Photo 3.