

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404056822

Date Received:

01/14/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10227
Name of Operator: CHOLLA PETROLEUM INC

Address: 12404 PARK CENTRAL DR STE 380S

City: DALLAS State: TX Zip: 75251

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tom Obenchain

214-455-4614

tao@chollapetro.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 701007976

Inspection Date: 01/17/2024

FIR Submit Date: 01/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CHOLLA PETROLEUM INC

Company Number: 10227

Address: PO BOX 12208

City: DALLAS

State: TX

Zip: 75225

LOCATION - Location ID: 314216

Location Name: MAGIWA UNIT-621S47W

Number: 23NENE

County: PROWERS

Qtrqtr: NENE

Sec: 23

Twp: 21S

Range: 47W

Meridian: 6

Latitude: 38.214100

Longitude: -102.653260

FACILITY - API Number: 05-099-

-00

Facility ID: 278882

Facility Name: MAGIWA UNIT

Number: 1-23

Qtrqtr: NENE

Sec: 23

Twp: 21S

Range: 47W

Meridian: 6

Latitude: 38.214100

Longitude: -102.653260

CORRECTIVE ACTIONS:

1 CA# 191109

Corrective Action: Install sign to comply with Rule 605.d.

Date: 02/17/2024

Response: CA COMPLETED

Date of Completion: 03/20/2024

Operator
Comment:

Operator has address the issue to comply with Rule 605.h

ECMC Decision:

Date: 1/14/2025 10:20:27 AM