

Inspection Photos
Operator: OWP-
Lake Brownhouse
Location ID: 448934
Date: 8/5/2024



Photo 1: View of the project area from the approximate wellhead facing northward. Smooth brome and Nuttall's alkaligrass are well established within the irrigated pasture.



Photo 2. View of the project area from the approximate wellhead facing southward.



Photo 3: View of the project location from the center facing southwestward.



Photo 4: View of the reference area comprised of irrigated pasture with vegetation approximately the same as project area.



Photo 5: View of the adjacent reference area comprised of horse pasture, largely in a grazed grasses and ruderal forbs.