

Inspection Photos

01/08/2025

Operator: PUBLIC SERVICE COMPANY OF
COLORADO - 72400

Location ID: 312383

Inspection Doc: 718100156

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the Location from southeast to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 2: Photos 2-5 examples showing anchors on the Location have not been marked in accordance with 603.j/1003.a requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383




Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



January 8, 2025



January 8, 2025

Photo 4: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 5: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 6: Photos 6-8 examples showing erosion degradation on the Location and access road has persisted; stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport remain missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



January 8, 2025



January 8, 2025

Photo 8: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312383



Photo 9: Photo shows hatch (arrow) at the produced water tank is open and currently venting to atmosphere.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources