

# Inspection Photos

01/08/2025

**Operator:** PUBLIC SERVICE COMPANY OF  
COLORADO - 72400

**Location ID:** 312597

**Inspection Doc:** 718100168

Mesa County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 1:** Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 3:** Photo shows hatch (arrow) at the produced water tank is open and currently venting to atmosphere.



**COLORADO**

Energy & Carbon Management  
Commission


Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 4:** Photos 4-5 examples showing anchors on the Location have not been marked in accordance with 603.j/1003.a requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 5:** See comments under photo 4.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 6:** Photos examples showing erosion degradation on the west end of the Location has persisted; stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport remain missing or insufficient.



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 7:** Photo examples showing erosion degradation on the west end of the Location has persisted; stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 8:** Photos examples showing erosion degradation on the south end of the Location has persisted; stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 9:** Photos examples showing erosion degradation at the access road has persisted; stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 312597



**Photo 10:** Photo shows trash/debris on the northeast end of the Location.