

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



When replaced additional information is required



Erosion and sediment migration

KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314

Jan 14, 2025 at 11:51:04 AM

Edl. 5957' Rio Blanco ROC 503

EMPACT ANALYTICAL SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO 80601
303-637-0150 www.empectanalytical.com

Meter S/N
15828411
C-59334

Station Name AHU 24-43
Station No. 120275592 Producer 310P
Sec 24 Township 2N Range 97W
Diff 250" Temp Range 0-150° Tube Size 2.006
Static 200# Absolute 11.84 psig

	Date	Orifice Plate Size	Meter Test Date	Sample Date
GM	3-7-18	0.500	3-7-18	3-7-18
KS	3-20-19	.500	3-20-19	3-20-19
	1-27-22	.500	1-27-22	



Calibration overdue

Oily waste

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Containment not maintained



Unlabeled tank

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Illegible label



Debris

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Oily waste and soil staining



When replaced additional information is required

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Debris



Weeds

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Weeds



Soil staining

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Location from Southeast corner



Location from Northeast corner

**KT Resources LLC
Ant Hill Unit 24-43
Location ID: 316314**



Location from Northwest corner



Location from Southwest corner