

# Inspection Photos

01/08/2025

**Operator:** PUBLIC SERVICE COMPANY OF  
COLORADO - 72400

**Location ID:** 390922

**Inspection Doc:** 718100180

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 390922



**Photo 1:** Photos taken from the east end of the Location. Photos provide an overview from southwest to west. Location is predominantly bare and exposed soils; vegetation establishment is not progressing towards 1004.c standards. What appears to be an Alkali crust has developed over the majority of the Location. Though similar soils are evident within the adjacent reference areas, concentrations appear to be much greater within the Location's disturbance area.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 390922



**Photo 2: Well marker on Location.**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: PUBLIC SERVICE COMPANY OF COLORADO - 72400

Location ID: 390922



**Photo 3:** Photo taken from the adjacent reference for comparison to the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources