

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404060056

Date Received:

01/16/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

QB Energy

ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905439

Inspection Date: 01/09/2025

FIR Submit Date: 01/10/2025

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334616

Location Name: PARKER RANCH-67S93W Number: 22SWNE County: _____

Qtrqtr: SWNE Sec: 22 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.434010 Longitude: -107.759860

FACILITY - API Number: 05-045- -00 Facility ID: 334616

Facility Name: PARKER RANCH-67S93W Number: 22SWNE

Qtrqtr: SWNE Sec: 22 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.434010 Longitude: -107.759860

CORRECTIVE ACTIONS:

1 CA# 201651

Corrective Action: Comply with CECMC pressure safety device rules

Date: 01/17/2025

Response: CA COMPLETED

Date of Completion: 01/15/2025

Operator Comment: Installed proper vent line on PRV. See photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 1/16/2025 9:26:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404060056	FIR RESOLUTION SUBMITTED
404060192	Installed proper vent line on PRV

Total Attach: 2 Files