

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 1/15/2025



Location Overview – Photo #06008



Location – Photo #06009

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 1/15/2025



Jan 15, 2025 at 14:09:24  
Parachute CO 81635  
United States



Jan 15, 2025 at 14:10:21  
Parachute CO 81635  
United States

Location – Photo #06012

Location – Photo #06014

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 1/15/2025



Location – Photo #06013



Vent Cover Stuck Open – Photo #06010