

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404056092

Date Received:

01/16/2025

Spill report taken by:

Brown, Kari

Spill/Release Point ID:

488164

**SPILL/RELEASE REPORT (SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

**OPERATOR INFORMATION**

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-0055</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>( )</u>
Zip: <u>80217-3779</u>		Email: <u>DJRemediation_Forms@oxy.com</u>
Contact Person: <u>Jaron Bartoszek</u>		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**Initial Spill/Release Report Doc# 403948338

Initial Report Date: <u>10/07/2024</u>	Date of Discovery: <u>10/07/2024</u>	Spill Type: <u>Recent Spill</u>
--	--------------------------------------	---------------------------------

**Spill/Release Point Location:**

QTRQTR SESW SEC 23 TWP 2N RNG 67W MERIDIAN 6

Latitude: 40.119299 Longitude: -104.863132

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☐ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

**Reference Location:**

Facility Type: TANK BATTERY ☒ Facility/Location ID No 436957

Spill/Release Point Name: MULGA 29C SMALL EYED 14C HZ O SA ☐ Well API No. (Only if the reference facility is well) 05- -

☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>Unknown</u>	Estimated Condensate Spill Volume(bbl): <u>Unknown</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>Unknown</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Sunny ~70s

Surface Owner: FEE Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On October 7, 2024, a release of unknown volume was discovered at the Mulga 29C Small Eyed 14C HZ O SA Production Facility location, due to fluid observed daylighting from the subsurface near the separator. Cleanup and site assessment activities are currently ongoing and will be summarized in a forthcoming Supplemental Form 19 Spill/Release Report. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. The State Notification email is provided as Attachment B.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
10/7/2024	Weld County	Weld County	-	Notified via email
10/7/2024	Surface Owner	Surface Owner	-	Notified via phone

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/13/2025		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, <b>including walls &amp; floor regardless of construction material</b>, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>24</u>		Width of Impact (feet): <u>18</u>	
Depth of Impact (feet BGS): <u>10</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
On October 7 through December 31, 2024, excavation and site investigation activities were conducted to address the soil impacts at the release location. Thirteen (13) soil samples were collected from the excavation area and were submitted for laboratory analysis of BTEX, naphthalene, TPH, 1,2,4- & 1,3,5-TMB, 1-methylnaphthalene (M), 2-M, Benzo (a) anthracene, Chrysene, Fluorene, Pyrene, boron, SAR, EC, As, Ba, Cd, Cu, Pb, and Ni based on the waste characterization profile created using the analytical results of sample WP01@3". Excavation and soil sampling activities are on-going and shall be reported along with final laboratory analytical results on a subsequent Form 27 supplemental. Soil sample location and field screening data are presented in Table 1. Partial soil analytical results are summarized in Tables 2 through 5. The soil sample locations are illustrated on Figure 2.			
Soil/Geology Description:			
Valent sand, 0 to 3 percent slopes			
Depth to Groundwater (feet BGS) <u>27</u>		Number Water Wells within 1/2 mile radius: <u>2</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1380</u> None <input type="checkbox"/>	Surface Water <u>2540</u> None <input type="checkbox"/>	
	Wetlands <u>1321</u> None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock <u>1610</u> None <input type="checkbox"/>	Occupied Building <u>925</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

## CORRECTIVE ACTIONS

#1	Supplemental Report Date: 01/13/2025
Root Cause of Spill/Release	Equipment Failure
Other (specify)	
Type of Equipment at Point of Spill/Release:	Horizontal Separator
If "Other" selected above, specify or describe here:	
Describe Incident & Root Cause (include specific equipment and point of failure)	
<div style="border: 1px solid black; padding: 5px;"> A release was discovered following the discovery of fluids daylighting from the subsurface at the Mulga 29C Small Eyed 14C HZ O SA Production Facility location, beneath one of the horizontal separators. Cleanup, site assessment, and site investigation activities are currently ongoing and will be summarized in a forthcoming Supplemental Form 19. Reporting shall be continued under the remediation number that is assigned to Form 27 Initial document no. 404051293. </div>	
Describe measures taken to prevent the problem(s) from reoccurring:	
<div style="border: 1px solid black; padding: 5px;"> The affected infrastructure has been removed for ongoing cleanup and site assessment activities and will be repaired and/or replaced. </div>	
Volume of Soil Excavated (cubic yards):	
Disposition of Excavated Soil (attach documentation)	<input type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment <input type="checkbox"/> Other (specify)
Volume of Impacted Ground Water Removed (bbls):	
Volume of Impacted Surface Water Removed (bbls):	

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:

- ☐ Corrective Actions Completed (documentation attached, check all that apply)
  - ☐ Horizontal and Vertical extents of impacts have been delineated.
  - ☐ Documentation of compliance with Table 915-1 is attached.
  - ☐ All E&P Waste has been properly treated or disposed.
- ☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_
- ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

Cleanup, site assessment, and site investigation activities are currently ongoing and will be summarized in a forthcoming Supplemental Form 19. Reporting shall be continued under the remediation number that is assigned to Form 27 Initial document no. 404051293.

Signed: \_\_\_\_\_ Print Name: Jaron Bartoszek

Title: Environmental Advisor Date: 01/16/2025 Email: DJRemediation\_Forms@oxy.com

Page 5 of 6

### ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
404057199	TOPOGRAPHIC MAP
404057200	SOIL SAMPLE LOCATION MAP
404057202	SOIL SAMPLE LOCATION MAP
404057203	ANALYTICAL RESULTS
404057204	ANALYTICAL RESULTS
404057205	ANALYTICAL RESULTS
404057212	ANALYTICAL RESULTS
404057214	ANALYTICAL RESULTS
404057215	ANALYTICAL RESULTS
404061339	PHOTO DOCUMENTATION

Total Attach: 10 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)