

# Final Reclamation Inspection

January 10, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 323356

Inspection Document #: 697505699

Weld County, CO

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SUSAN #1-23  
Location ID: 323356



**Photo 1.** Photo illustrates all oil and gas equipment has been removed. Surface owner is using the tank battery for storage of ag. equipment.

At the time of this inspection, there were no stormwater or weed issues.



**Photo 2.** Photo illustrates aboveground midstream equipment remains and appears to be active.

