

## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



Jan 13, 2025 at 12:11:30 PM  
+39.207556,-107.894986 ±9.25m  
Collbran

Photo # 2535 Entrance to location



Jan 13, 2025 at 12:32:02 PM  
+39.207684,-107.894749 ±5.91m  
Collbran

Photo # 2557 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



Photo # 2536 Location



Photo # 2540 Location





## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



Photo # 2555 Location



Photo # 2561 SW corner of location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



Photo # 2563 SE corner of location



Photo # 2565 NE corner of location



## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



Photo # 2566 NW corner of location




Photo # 2546 Equipment has been modified and is not being operated in a safe manner

## Inspection Photos

Location: LARAMIE ENERGY LLC Esperanza/9-5 Pad

Location ID: 334510

Date: 01/13/2025



**Photo # 2550 Equipment has been modified and is not being operated in a safe manner**



**Photo # 2551 Equipment has been modified and is not being operated in a safe manner**