

## Inspection Photos

Location Name: QB Energy SAVAGE 1-14 (RA1) Pad

Location #: 334747



Photo # 8370 From entrance to location




Photo # 8371 Location



**Inspection Photos**  
**Location Name: QB Energy SAVAGE 1-14 (RA1) Pad**  
**Location #: 334747**




**Photo # 8372 Location**



**Photo # 8373 Location**





**Location #: 334747**

### Photo # 8375 Location

## Inspection Photos

Location Name: QB Energy SAVAGE 1-14 (RA1) Pad

Location #: 334747



**Photo # 8376 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**

