

Inspection Photos
Location Name: Korf* R 43-08 4N46W
API Number: 125-09805



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Korf* R 43-08 4N46W
API Number: 125-09805



3. Well location overview.



4. View of meter shed missing door. Door is on ground inside fencing.

Inspection Photos
Location Name: Korf* R 43-08 4N46W
API Number: 125-09805



5. Calibration card with incorrect API number.