

Inspection Photos

API: 061-06149

Operator: CIMARRON OIL & GAS CO INC

Inspection Date: 1/14/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the location. There is an abandoned pipe riser that remains.



Inspection Photos




Photo 2. Facing east at the location. Another abandoned pipe riser remains. Red arrows point to both pipe risers.



Inspection Photos



Photo 3. Facing north toward the former access road. This area had previously eroded but now has been stabilized with native vegetation.

