

# Inspection Photos

Loc: 324789

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/14/2025

County: Kiowa




## Inspection Photos



**Photo 1.** Facing northwest along the access road toward the location. This area of the road is rutted and will require maintenance.



## Inspection Photos



**Photo 2.** Facing southeast toward the storage shed adjacent to the tank battery. The side of the shed has been repaired.



## Inspection Photos



**Photo 3.** Facing inside the north side of the building. There is still various supplies and debris which must be cleaned up.



Inspection Photos



January 14, 2025  
+38.431408,-102.479402  
Kiowa County  
ECMC

**Photo 4.** View of inside middle are of the shed. This area has been leaned out and pipe is stored inside.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324789 | Date: 1/14/2025

## Inspection Photos



**Photo 5.** Standing at the wellhead facing east. Sign is posted at wellhead.

