

# Interim Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 409555

Well Name: HSR-AMATO #4-1

Inspection Document #: 718600154

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-AMATO #4-1  
Location ID: 409555



**Photo 1.** Looking south across tank battery. Bottles and other trash is present throughout the location.



**Photo 2.** Tumbleweed touching separator.



Inspection Photos  
Location Name: HSR-AMATO #4-1  
Location ID: 409555



**Photo 3.** looking south at tank battery.



**Photo 4.** Open bucket containing oily waste near partially buried produced water tank.

Inspection Photos  
Location Name: HSR-AMATO #4-1  
Location ID: 409555



**Photo 5.** looking south at southern edge of location. Black trash bag is present. List B noxious weed Scotch thistle rosettes are also present in this area.



**Photo 6.** Looking north along eastern edge of location. Undesirable weedy plants Russian thistle and Kochia are present around the perimeter of this location.

