

# Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024



Photo # 2642 Entrance to location




Photo # 2673 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024



Photo # 2644 Location



Photo # 2649 Location

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024



Photo # 2672 Location



Photo # 2681 NE corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024



Photo # 2682 NW corner of location



Photo # 2683 SW corner of location

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024




Photo # 2684 SE corner of location



Photo # 2655 Wildlife hazard

## Inspection Photos

Location: LARAMIE ENERGY LLC CC/0629-31-11 Pad

Location ID: 335090

Date: 01/14/2024



Photo # 2660 Unused equipment



Photo # 2670 Debris