



ORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- 087 - 8095	LEASE NAME: Danford #1
LOCATION: SE NW 9-24-58	OPERATOR: Western / O'Brien
DATE: 5-28-96	INSPECTOR: E. Bialley
Insp. Type: DG Insp. Status: ND PA: Y N	Pass/Fail: P F Viol.: Y N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	<i>New location built by</i>	<input checked="" type="checkbox"/>
Pits (Reserve/Production) (Rule 902, 903, 904)	<i>D.C. Dozer, Dule Putman</i>	
Fences (Rule 604.C.(3), 1003.A)	<i>2040 FAL 1980 FAL</i> JUL 10 1995	
Tank Battery Equipment (Rule 604)	<i>Moving rig tomorrow</i>	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: *Permit required prior to work.*

Date Corrective Action Required By: _____ Date Remedied: _____

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.