

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Photo # 9284 From entrance to location



Photo # 9285 From entrance to location

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617




Photo # 9286 Location



Photo # 9287 Location

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Photo # 9288 Location



Photo # 9289 Location

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Jan 15, 2025 at 3:28:45 PM
CO

Photo # 9290 Location



Jan 15, 2025 at 3:20:38 PM
CO

Photo # 9291 Open ended load line



Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Photo # 9292 Hole in liner/liner needs maintenance



Photo # 9293 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Photo # 9294 Hole in liner/liner needs maintenance



Photo # 9295 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: QB Energy PARKER RANCH (H15) Pad
Location ID: 334617



Photo # 9296 Hole in liner/liner needs maintenance



Photo # 9297 Hole in liner/liner needs maintenance