

Inspection Photos
Location Name: Al Ward 2-36
API Number: 125-07445



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Al Ward 2-36
API Number: 125-07445



3. Well location overview.



4. Gathering location overview. Note run off soil erosion around remote gas meter shed.

Inspection Photos
Location Name: Al Ward 2-36
API Number: 125-07445



5. View of roof damage to remote gas meter shed.



6. View of Gas Meter inside remote gas meter shed.

Inspection Photos
Location Name: Al Ward 2-36
API Number: 125-07445



7. View of Flow Meter Face. No power to meter for gas measurement.



8. View of valve at remote meter shed. Both valves, Inlet and Outlet open at time of inspection.