

Inspection Photos

January 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325412

Inspection Document #: 714001709

La Plata County, CO

Township: NESW 35 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Richardson E2
Location ID: 325412



Photo 1. View of well pad taken from the access point facing center.



API #: 067-06338

Inspection Photos
Location Name: Richardson E2
Location ID: 325412



Photo 2. Produced water tank label is peeling and no longer legible.

Inspection Photos
Location Name: Richardson E2
Location ID: 325412



Photo 3. Impacted surface material observed at well head.

Inspection Photos
Location Name: Richardson E2
Location ID: 325412



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Eastern interim reclamation area composed of Western Wheatgrass, Indian Ricegrass and Broom Snakeweed.

API #: 067-06338

Inspection Photos
Location Name: Richardson E2
Location ID: 325412



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Black Sagebrush, Broom Snakeweed, Western Wheatgrass and Crested Wheatgrass.

API #: 067-06338