

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



1. Lease sign at well location.



2. View of wellhead.



Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



5. View of roof damage to separator shed.



6. View of produced water tank at gathering location.

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



7. Gas meter inside meter shed.



8. Calibration log with incorrect well API number.

Inspection Photos
Location Name: RMR Ranch 2
API Number: 125-07290



9. Gathering location overview.



10. Gathering location overview.