

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Jan 16, 2025 at 12:34:01 PM  
CO



Jan 16, 2025 at 12:34:09 PM  
CO

Photo # 9670 From entrance to location

Photo # 9671 From entrance to location

## Location # 311612



### Photo # 9673 Location



## Inspection Photos


Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Jan 16, 2025 at 12:46:40 PM  
CO

Photo # 9674 Location



Jan 16, 2025 at 12:40:20 PM  
CO

Photo # 9675 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Photo # 9676 Location



Photo # 9677 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Jan 16, 2025 at 12:37:06 PM  
CO

Photo # 9678 Location



Jan 16, 2025 at 12:35:16 PM  
CO

Photo # 9679 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Photo # 9680 Location



Photo # 9681 Debris



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Photo # 9682 Debris



Photo # 9683 Unused hose in secondary containment

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Photo # 2706 From inspection 708905240 conducted on 12/06/2024 Open ended load line



Photo # 9684 Open ended hose/load line - additionally this is also a wildlife hazard



## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



Photo # 2707 From inspection 708905240 conducted on 12/06/2024 Open ended load line



Photo # 9685 Open ended hose/load line - additionally this is also a wildlife hazard

## Inspection Photos

Location Name: TEP Rocky Mountain LLC LAST DANCE 12-2

Location # 311612



**Photo # 9686 New tank label missing required information/  
not in compliance with CECMC rules**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources