

# Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 311979

Inspection Document #: 714001711

La Plata County, CO

Township: SESE 1 1 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
 Location Name: Simmons A2, 3, 4  
 Location ID: 311979



1/14/25  
 85° E



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos  
Location Name: Simmons A2, 3, 4  
Location ID: 311979



**Photo 2.** Wattles on the western edge of the pad are disintegrating are not longer functioning.

Inspection Photos  
Location Name: Simmons A2, 3, 4  
Location ID: 311979



**Photo 3.** Signs/Labels at separator and produced water tank are deteriorating, future maintenance is advised.

Inspection Photos  
Location Name: Simmons A2, 3, 4  
Location ID: 311979

1/14/25  
77° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Interim vegetation was not fully assessed due to snowy conditions, however Rabbitbrush was observed on location.

API #: Multi Well