

Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326341

Inspection Document #: 714001722

La Plata County, CO

Township: NWSE 2 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bonifacio Gallegos A1
Location ID: 326341

1/14/25
44° NE



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos

Location Name: Bonifacio Gallegos A1

Location ID: 326341




Photo 2. Large patch of flowered/seeded Musk Thistle observed on location.

Inspection Photos
Location Name: Bonifacio Gallegos A1
Location ID: 326341



Photo 3. Culvert on the northern edge of the pad has filled with sediment and is no longer functioning properly.

Inspection Photos
Location Name: Bonifacio Gallegos A1
Location ID: 326341

1/14/25
199° S



Photo 4. Reference area composed of Big Sagebrush, Rubber Rabbitbrush and Broom Snakeweed.