

Inspection Photos

January 14th, 2024

Operator: Logos Operating - 10679

Location ID: 325159

Inspection Document #: 714001725

La Plata County, CO

Township: NESW 10 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ignacio 33-8 5
Location ID: 325159



Photo 1. View of wellhead assembly.



LOGOS OPERATING, LLC.
IGNACIO 33-8 #005 DK MV
FEE
API NO. 05-067-05476
2310' FSL & 2310' FWL
SEC.10 T33N R08W N4PM
LA PLATA COUNTY, CO
LAT: 37.11771 LONG: 107.70588
EMERGENCY CONTACT # 1-866-598-9226 OR 911
FROM INTERSECTION OF CR314 GO SOUTH
ON CR311, 0.5 MILE, CONTINUE SOUTH ON
SAGEWOOD DRIVE 1.4 MILES TO LOCATION

API #: 067-05476

Inspection Photos
Location Name: Ignacio 33-8 5
Location ID: 325159

1/14/25
222° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Interim reclamation composed of Sand Dropseed and Rubber Rabbitbrush.

API #: 067-05476

Inspection Photos
Location Name: Ignacio 33-8 5
Location ID: 325159



Photo 3. Marked guyline anchor on location.

Inspection Photos
Location Name: Ignacio 33-8 5
Location ID: 325159

1/14/25
159° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Rubber Rabbitbrush, Sagebrush and Prairie Sunflower.

API #: 067-05476