

Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326338

Inspection Document #: 714001727

La Plata County, CO

Township: NENW 3 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Klusman A1
Location ID: 326338



Photo 1. View of well pad from the access point facing center.

Inspection Photos
Location Name: Klusman A1
Location ID: 326338

1/14/25
234° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Vegetation was not fully assessed due to snowy conditions, however no weedy debris were observed on location.

API #: 067-07862