

# Inspection Photos

January 14th, 2024

Operator: Simcoe LLC - 10749

Location ID: 311951

Inspection Document #: 714001728

La Plata County, CO

Township: NWSE 34 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Klusman 33-34 1, 3  
Location ID: 311951



Photo 1. View of well pad from the access point facing center.



Inspection Photos  
Location Name: Klusman 33-34 1, 3  
Location ID: 311951



**Photo 2.** View of wellhead assembly free of weedy debris.

Inspection Photos  
Location Name: Klusman 33-34 1, 3  
Location ID: 311951



Photo 3. Produced water tank label is peeling, future maintenance is advised.

Inspection Photos  
Location Name: Klusman 33-34 1, 3  
Location ID: 311951

1/14/25  
76° E



**Photo 4.** Label at separator has deteriorated and is no longer legible.

Inspection Photos  
Location Name: Klusman 33-34 1, 3  
Location ID: 311951



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Interim reclamation composed of Western and Intermediate Wheatgrass.

API #: 067-07896, 09421

1/14/25  
66° NE



**Photo 6.** Active cow pasture reference area composed of grazed grasses.