



99999999

**OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801


☒ NOTICE OF SATISFACTORY INSPECTION

Denver, CO 80203

(303)894-2100

| | |
|---------------------------|-------------------------------------|
| API No. 05- (087 - 07456) | LEASE NAME: Peterson A-2 |
| LOCATION: SENE 34-2N-56 | OPERATOR: OKMHR |
| DATE: 8-29-96 | INSPECTOR: Ed Binkley (970) 8424465 |
| Insp. Type: HR | Insp. Status: DA |
| PA: X N | Pass/Fail: (P) F |
| Viol.: Y (N) | NOV: Y (N) |

INSPECTION ITEM**COMMENTS****INPUT**

| | | |
|--|---|--|
| Well ID Signs (Rule 210) | SCANNED | |
| Pits (Reserve/Production) (Rule 902, 903, 904) | | |
| Fences (Rule 604.C.(3), 1003.A) | | |
| Tank Battery Equipment (Rule 604) | | |
| Fire Walls/Berms/Dikes (Rule 604) | | |
| General Housekeeping (Rule 603.G) | | |
| Spills (Oil/Water) (Rule 908) | | |
| Bradenhead (Rule 207) |  | |
| Drilling Well/Workover (Rule 315) | | |
| Surface Rehabilitation (Rule 317) | grass - 50% | |
| Miscellaneous | | |

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site