

WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

Well Name Marguardt #1 API Number 05 - 087 - 5588  
Operator Martahan Permit # \_\_\_\_\_  
Location SWSE 29-2N-57 County Morgan  
Field Albana Inspector Binley



AL/PA/DA Inspection Results:

Well Status:

SCANNED

Pass(Y) \_\_\_\_\_ Fail(N) \_\_\_\_\_ Date \_\_\_\_\_ ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR ☒ SI \_\_\_\_\_ TA \_\_\_\_\_

=====

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection



Date Plugged: \_\_\_\_\_ Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bond Release OK: Yes \_\_\_\_\_ No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

Date of Safety/Status Inspection ~~7-2-91~~

Comments: See  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Violations: Yes \_\_\_\_\_ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_