

Inspection Photos
Location Name: McMillen Trust 19-13G
Location ID: 327599



Photo 1: Wellhead Sign

Photo 2: Wellhead

Inspection Photos
Location Name: McMillen Trust 19-13G
Location ID: 327599



Photo 3: Tank Battery Sign

Photo 4: Tank Battery

Inspection Photos
Location Name: McMillen Trust 19-13G
Location ID: 327599



Photo 5: Unused equipment