

# Final Reclamation Inspection

January 10, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 331020

Inspection Document #: 697505705

Weld County, CO

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lorenz PC/F22-33D  
Location ID: 331020



**Photo 1.** Photo taken along the northern tank battery, facing North. Photo illustrates the tank battery is in-process of establishing desirable vegetation.



## Inspection Photos

Location Name: Lorenz PC/F22-33D

Location ID: 331020



**Photo 2.** Photo taken along the eastern portion of the access road, facing West. Photo illustrates the access road has been interseeded with the evidence of drill rows.



**Photo 3.** Photo taken along the midway portion of the access road, facing West. See comments under Photo 2.

