

Inspection Photos
Location Name: Jillson 5
Location ID: 318491



Photo 1 Location



Photo 2 Circulation tanks, rig pump.

Inspection Photos
Location Name: Jillson 5
Location ID: 318491



Photo 3 Pipe trailer, WO rig.



Photo 4 Cement equipment & fresh water transport.

Inspection Photos
Location Name: Jillson 5
Location ID: 318491



Photo 5 Rig crew prepping WH for cement.



Photo 6 Cement equipment.